Approved For Release 2003/12/23: CIA-RDP66B00664R00400020044-7 S E C R E T 2138Z 66 MAR 64 S E C R E T 2138Z 66 MAR 64 TO : DIRECTOR 25X1A ROUTINE ROUTINE IN 66412	outograd ung prepudus gad karriuns			MFC, 6-63
SECRET 2158Z 06 MAR 64 SECRET 2 10 3 11 4 12 5 13 FROM: ACTION: OPS /- () ROUTINE IN 66412	Sand Sanda Sandan	CLASSIFIED MESSAGE		ROUTING
2138Z 06 MAR 64 2138Z 06 MAR 64 70 : DIRECTOR 25X1A FROM: ACTION: OPS /- () IN 66412	Approved For Release	2003/12/23 : CIA-RDP66B00664R	00400020044-7	Ģ
2138Z 96 MAR 64 2138Z 96 MAR 64 112 13 14 12 13 14 15 13 14 7 15 ROM: ROM: ROWTINE IN 66412	SATE .		2	10
TO : DIRECTOR		.)	3	11
O : DIRECTOR 25X1A ROM : ROW : ROUTINE IN 66412	2138Z Ø6 MAR 64	Перевы переводного пентинов се негова почто видент и почтова не негования при при при почто на почто на почто н Петем переводителните негова почто негова		12
25X1A ROM: ROM: ROW : ROUTINE IN 66412	gana daggagan kabangan kempangan menanggan penanggan penanggan penganggan penganggan penganggan penganggan bel Banas kempanggan penganggan bengan penganggan penganggan penganggan penganggan penganggan penganggan pengangga	мый ж. М. 1820-ж. т. т. т. т. ж. 19 г. 2004 года остада остада останования принципальный постанова общений вып 1920-ж. 1920-ж. п. т. т. т. т. т. т. станова остана постанования принципальный постанования постанования поста	5	13
25X1A ROM: ROWTINE ROUTINE IN 66412	n . DIRECTOR	•	6	and with the second
ROM: ACTION: OPS)-1 ROUTINE ROUTINE IN 66412			7	
ROUTINE ROUTINE IN 66412.	j		B I	
IN 66412			ROUTINE	
	MFO :	*·	The second secon	
IOR'S 2002 G WAN OF	TOR: 2353Z 6 MAR 64			IN 664125X1

25X1A:

SUBJECT: FILM EVALUATION MISSION S074E.

- 1. CAMERA B 10 WAS USED IN MISSION S074E FLOWN ON 1 MARCH 1964;
 PROCESSING WAS ACCOMPLISHED BY ______ 25X1A
 - 2. ORIGINAL NEGATIVE:
- A. THE EXPOSURE IS ADEQUATE AND THE RESOLUTION IS FAIR TO GOOD DUE TO ATMOSPHERIC CONDITIONS.
- B. 9R SIDE: THE FILM WAS RECEIVED AT THE PROCESSING SITE WITH INTERMITTENT MINOR CREASES AND SMALL TEARS ALONG BOTH EDGES POSSIBLY DUE TO THE FILM MISTRACKING. THIS DAMAGE IS LESS THAN THAT REPORTED ON MISSION 0064E. NUMEROUS SHORT PLUS DENSITY STREAKS OF VARIOUS LENGTHS AND LOCATED RANDOMLY ACROSS THE FORMAT ARE NOTICEABLE IN LOW DENSITY FRAMES. TWO ALTERNATING PLUS DENSITY STREAKS, PARALLEL TO THE FILM EDGES, ARE PRESENT 3.3" FROM THE OUTBOARD EDGE AND 3.25" FROM THE INBOARD EDGE OF THE FILM THROUGHOUT. A ROW OF MINUS DENSITY DOTS, SPACED 1.55" APART, ARE PRESENT 1.6" FROM THE AND PARALLEL TO THE OUTBOARD EDGE OF THE FILM THROUGHOUT. A WAVERING PLUS DENSITY STREAK, APPROXIMATELY 6.25" LONG, IS PRESENT IN FRAMES 1290

SECRET

CREATE 1 Included from automotic downgreding and declaration Approved For Release 2003/12/23: CIA-RDP66B00664R089400020044-7

25X1A

1935 (IN 66412) SECRET PAGE TWO

AND 1323. NANUFACTURER'S SPLICES ARE PRESENT IN FRANES 2394 AND 2728.

- C. 9L SIDE: A WAVERING MINUS DENSITY STREAK OCCURS ALONG THE INBOARD EDGE OF THE FILM ON FRAME 801 TO THE MANUFACTURER'S SPLICE IN FRAME 805. TWO ROWS OF MINUS DENSITY DOTS, SPACED 1.55" APART. OCCUR 0.1" AND 3.2" FROM AND PARALLEL TO THE INBOARD EDGE OF THE FILM THROUGHOUT. MANUFACTURER'S SPLICES ARE PRESENT IN FRAMES 1983 AND 3152.
 - D. BOTH SIDES: FRAMES ARE TITLED 0000 THROUGH 3258.
- E. THERE WERE NO MAJOR CAMERA MALFUNCTIONS OR PROCESSING FROBLEMS ENCOUNTERED DURING THIS MISSION.
 - 3. POSITIVE:
- A. PI SUITABILITY IS GOOD WHERE NOT DEGRADED BY CLOUDS AND HAZE.
 - B. PRINTING AND PROCESSING ARE GOOD.
- C. CLOUDS OBSCURE OR DEGRADE APPROXIMATELY 25 PERCENT OF THE MISSION.

END OF MESSAGE

SECRET